


Service Manual

CD17AK /N2B, /N2G

Compact Disc Player

CD-17mkII KI



REMARK : This service manual explains the differences between the 74CD17/22B/22G (CD-17MKII) and the CD17AK/N2G/N2B (CD-17MKII KI).

All other information is described in the service manual of the model 74CD17/22B/22G (Code number : **4822 725 51178**). The dispatch of the parts for after sales service has to be referred to these service manuals, with the first priority.

For this reason, please use this service manual with referring to the model CD17MKII service manual without fail.

The CD-17MKII KI is equal to the CD-17MKII except the following changes :

POS. NO	VERS. COLOR	PART NO. (FOR PCS)	DESCRIPTION	PART NO. (MJI)	POS. NO	VERS. COLOR	PART NO. (FOR PCS)	DESCRIPTION	PART NO. (MJI)
			PP16-AUDIO/POWER CIRCUIT BOARD					EXPLODED VIEW	
C613		9965 000 08115	330μF 16V ARS	OA33701640	001B	BLACK	9965 000 11397	FRONT PANEL ASSY BLK	356K248520
C614		9965 000 08115	330μF 16V ARS	OA33701640	001B	GOLD	9965 000 11398	FRONT PANEL ASSY GLD	356K248530
C663		9965 000 08115	330μF 16V ARS	OA33701640	004B		nsp	BRACKET	nsp
C664		9965 000 08115	330μF 16V ARS	OA33701640	005B		nsp	BRACKET	nsp
J601	Removed		RCA JACK L/R GOLD YKC21-3337	Removed	001G		nsp	CHASSIS	nsp
J602		4822 290 61214	RCA 1P GOLD REAR PANEL	YT02010820	002G		nsp	BOTTOM COVER	nsp
J603		4822 290 61214	RCA 1P GOLD REAR PANEL	YT02010820	901G	BLACK	nsp	REAR PANEL BLACK	nsp
DN09	Removed		DIODE 1SS176 MA165 1SS254 30V 0.1A	Removed	901G	GOLD	nsp	REAR PANEL GOLD BROWN	nsp
DN10			DIODE ZENER 3.9V	HD30391000	▲L001		9965 000 08116	MAINS TRANSFORMER TROIDAL 230V	TS46009060
RN03	Removed		RES. 1kΩ ±5% 1/6W	Removed					
RN04	nsp		RES. 10kΩ ±5% 1/16W	NN05103610					

Please use this service manual with referring to the user guide (D.F.U.) without fail.

marantz®

CD-17mkII KI (/N2B/N2G)